

HISTORIC AMERICAN ENGINEERING RECORD
INDEX TO PHOTOGRAPHS

HAER
KANS.
44-MER1.V,
1-

Meriden Rock Creek Bridge
Meriden Vicinity
Jefferson County
Kansas

HAER No. KS-2

Documentation: 13 exterior photos (1981)
6 data pages (1981)

Steve Wilde, Photographer - June 4, 1981

KS-2-1 GENERAL VIEW OF WEST SIDE
KS-2-2 WEST SIDE OF ABUTMENTS
KS-2-3 VIEW FROM NORTH TOWARDS SOUTH ACROSS TRAFFIC DECK
KS-2-4 DETAIL OF CONNECTIONS ON TOP CHORD OF PARABOLIC BOWSTRING ARCH
KS-2-5 DETAIL OF CONNECTIONS ON TOP CHORD
KS-2-6 DETAIL OF COMPRESSION MEMBERS
KS-2-7 DETAIL OF SOUTH ABUTMENT AND FLOOR SUPPORT
KS-2-8 DETAIL OF NORTH ABUTMENT AND FLOOR SUPPORT
KS-2-9 DETAIL OF STONE WORK ON SOUTH ABUTMENT
KS-2-10 DETAIL OF TRUSS SUPPORT COLUMN ON NORTH ABUTMENT
KS-2-11 DETAIL OF CRACKED WING WALL ON NORTH ABUTMENT
KS-2-12 DETAIL OF VARIOUS CONNECTIONS ON LOWER CHORD OF ARCH TRUSS
KS-2-13 DETAIL OF COMPRESSION AND TENSION CONNECTIONS ON LOWER CHORD
OF ARCH TRUSS